

Work History

Registration/Fleet ID	LGZ7507	Asset No.	AAEJ8342
Make/Model	PEUGEOT EXPERT LONG DIESEL (2017) 1400 2.0 BlueHDi 120 Professional Plus Van		
Latest Odo Reading	185387	Odo Reading Date	09 Apr 2026
Contract Start Date	09 Jan 2019	Contract End Date	08 May 2026

Date	Service Centre	Line Item Description
08 Apr 2026	Roadside Motors Peugeot Portadown	Front Hub - Remove & Refit, Hub bearing(s) (one wheel) (Front Susp.) left
Odo Reading	185387	
Invoice No.	2020133	
Authority Ref.	9465717	
Job Ref.	154967348	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
05 Dec 2025	Charles Hurst Peugeot Boucher Road	Checks - Check, Investigate & Report
Odo Reading	178009	Abs Components - Remove & Refit, ABS wheel sensor (rear) left
Invoice No.	26317772	
Authority Ref.	9368935	
Job Ref.	151934335	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
07 Jul 2025	Charles Hurst Peugeot Boucher Road	Engine Assembly - Remove & Refit, Auxiliary drive belt (polyrib belt)
Odo Reading	164183	12 year Service
Invoice No.	26314521	Hydraulic Fluid - Remove & Refit, Hydraulic fluid (Brake)
Authority Ref.	9261319	MOT - Class IV Cars (Up To 8 Passenger Seats)
Job Ref.	147132952	Test Date:17 Jul 2025
Job Status	Payment Requested	Certificate No:22517804
		Lamps - Check & Adjust, Headlamp alignment
		Pipe - Remove & Refit, Metal brake pipes
		Front Hub - Remove & Refit, Hub bearing(s) (one wheel) (Front Susp.) left
		Wash/Wipe Systems - Remove & Refit, Windscreen wiper - blade/s
		Sensors - Remove & Refit, Coolant Flush

Date	Service Centre	Line Item Description
11 Jun 2025	Autoglass Bedford	P 1 PSERUK00581A
Odo Reading	0	P 1 PCON12096A
Invoice No.	043576764	P 1 PSER00400A
Authority Ref.		P 1 6569AGAIMVZ1C
Job Ref.	11864245	
Job Status	Complete	

Date	Service Centre	Line Item Description
14 Apr 2025	Charles Hurst Peugeot Boucher Road	Checks - Check, Investigate & Report
Odo Reading	159000	All Exhaust Components - Remove & Refit, Diesel particulate filter
Invoice No.	26312540	Disc (incl. pads) - rear (pair) (wheels removed)
Authority Ref.	9179327	
Job Ref.	144666565	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
21 Feb 2025	ITMS247LTD-I247PANEL - WFM Solutions	P 1 Environmental Disposal
Odo Reading	154238	P 1 Tubeless Valve
Invoice No.	SIN1538114	P 1 Alloy Wheel Balance
Authority Ref.		P 1 215/60 17 109T VAN Michelin AGILIS 3
Job Ref.	11697984	
Job Status	Complete	

Date	Service Centre	Line Item Description
03 Feb 2025	Charles Hurst Peugeot Boucher Road	Door (Side) - Remove & Refit, Door assy - side loading - hinge/sliding mechanism
Odo Reading	150621	
Invoice No.	26310629	
Authority Ref.	9115458	
Job Ref.	142945040	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
20 Dec 2024	Charles Hurst Peugeot Boucher Road	150000 mls/kms Service
Odo Reading	150621	
Invoice No.	26309902	
Authority Ref.	9081003	
Job Ref.	141524027	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
10 Jul 2024	Charles Hurst Peugeot Boucher Road	Wiring Harness - Remove & Refit, Harness - main/face
Odo Reading	131243	Front Hub - Remove & Refit, Hub bearing(s) (one wheel) (Front Susp.) left
Invoice No.	26306705	
Authority Ref.	8952478	
Job Ref.	137120452	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
13 Jun 2024	Charles Hurst Peugeot Boucher Road	Engine Management Fault Diagnosis - Check, Engine management - fault diagnosis
Odo Reading	131242	Abs Components - Remove & Refit, ABS wheel sensor (rear) right
Invoice No.	26305789	
Authority Ref.	8914799	
Job Ref.	136033341	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
08 Apr 2024	Bells Peugeot Crossgar	Charging circuit - alternator/dynamo
Odo Reading	127190	Engine Assembly - Remove & Refit, Auxiliary drive belt (polyrib belt)
Invoice No.	01153648	
Authority Ref.	8851064	
Job Ref.	134574634	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
06 Mar 2024	Bells Peugeot Crossgar	Adblue - Remove & Refit, AdBlue fluid
Odo Reading	124925	Sensors - Remove & Refit, Parking sensor - front inner right
Invoice No.	01153394	125000 mls/kms Service - 2016/- Expert (higher mileage - 25,000 miles intervals)
Authority Ref.	8841731	
Job Ref.	133371302	
Job Status	Payment Requested	Hydraulic Fluid - Remove & Refit, Hydraulic fluid (Brake)

Date	Service Centre	Line Item Description
17 Jan 2024	Roadside Motors Ltd Peugeot Lisburn	Flywheel - Remove & Refit, Flywheel/drive plate
Odo Reading	119615	Clutch Unit/Cable - Remove & Refit, Clutch release/withdrawal bearing
Invoice No.	209525	
Authority Ref.	8787579	
Job Ref.	131827831	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
04 Oct 2023	Roadside Motors Peugeot Portadown	Adblue - Remove & Refit, AdBlue fluid
Odo Reading	109721	Checks - Check, Investigate & Report
Invoice No.	2014482	
Authority Ref.	8682542	
Job Ref.	129529791	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
26 Sep 2023	ATS CH ARVAL DEALERS	P 1 Dunlop 215/60 R 17 T ECODRIVE TL (CB2-70dB)
Odo Reading	108902	P 1 Tyre Valve
Invoice No.	11431744	P 1 Wheel Balance
Authority Ref.		P 1 Casing Disposal
Job Ref.	10613545	P 1 Wheel Balance
Job Status	Complete	P 1 Dunlop 215/60 R 17 T ECODRIVE TL (CB2-70dB)
		P 1 Tyre Valve
		P 1 Dunlop 215/60 R 17 T ECODRIVE TL (CB2-70dB)
		P 1 Casing Disposal
		P 1 Wheel Balance
		P 1 Tyre Valve
		P 1 Casing Disposal

Date	Service Centre	Line Item Description
12 Jan 2023	Roadside Motors Peugeot Portadown	Windscreen wiper - blade/s
Odo Reading	105200	
Invoice No.	2012969	
Authority Ref.	8450625	
Job Ref.	122943067	
Job Status	Payment Requested	
Date	Service Centre	Line Item Description
05 Aug 2022	Roadside Motors Peugeot Portadown	Shock absorber/damper (pair) (Rear Susp.) Windscreen wiper - blade/s
Odo Reading	105189	
Invoice No.	2012153	
Authority Ref.	8311301	
Job Ref.	119306491	
Job Status	Payment Requested	
Date	Service Centre	Line Item Description
24 Mar 2022	Roadside Motors Peugeot Portadown	Disc (incl. pads) - front (pair) (wheels removed) Linings (Pads & Shoes) - Remove & Refit, Pads - rear (axle set) 100000 mls/kms Service
Odo Reading	104625	
Invoice No.	2011523	
Authority Ref.	8213432	
Job Ref.	115671960	
Job Status	Payment Requested	
Date	Service Centre	Line Item Description
26 Jan 2022	A A Breakdown	P 1 BOSCH AGM S5A08 (096)
Odo Reading	104583	
Invoice No.	201078421	
Authority Ref.		
Job Ref.	8656360	
Job Status	Complete	
Date	Service Centre	Line Item Description
22 Dec 2020	Roadside Motors Peugeot Portadown	Braking System Fault Diagnosis - Check, ABS - read fault codes Abs Components - Remove & Refit, ABS wheel sensor (rear) left Other Unspecified Work - Remove & Refit, Suspension - Shock Absorber Bush
Odo Reading	101743	
Invoice No.	208743	
Authority Ref.	7826409	
Job Ref.	107951685	
Job Status	Payment Requested	
Date	Service Centre	Line Item Description
26 Aug 2020	ATS CH ARVAL DEALERS	P 1 Tubeless Valve P 1 Puncture Repair P 1 Wheel Balance
Odo Reading	0	
Invoice No.	10891539	
Authority Ref.		
Job Ref.	7378316	
Job Status	Complete	

Date	Service Centre	Line Item Description
19 Aug 2020	Roadside Motors Peugeot Portadown	Front Hub - Remove & Refit, Wheel stud (front)
Odo Reading	88205	
Invoice No.	207858	
Authority Ref.	7703537	
Job Ref.	105591109	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
08 Jun 2020	Bells Peugeot Crossgar	75000 mls/kms Service
Odo Reading	81617	Auxiliary drive belt tensioner
Invoice No.	129779	Adblue - Remove & Refit, AdBlue fluid
Authority Ref.	7647407	
Job Ref.	104085138	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
12 May 2020	ATS CH ARVAL DEALERS	P 1 Wheel Balance
Odo Reading	77066	P 1 Casing Disposal
Invoice No.	10839779	P 1 Tyre Valve
Authority Ref.		P 1 Casing Disposal
Job Ref.	7234574	P 1 Wheel Balance
Job Status	Complete	P 1 NEWTYRE
		P 1 Tyre Valve
		P 1 NEWTYRE

Date	Service Centre	Line Item Description
12 Dec 2019	Roadside Motors Peugeot Portadown	Pads - front (axle set) (wheels removed)
Odo Reading	55953	
Invoice No.	0WI00121	
Authority Ref.	7525972	
Job Ref.	101770103	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
19 Nov 2019	Roadside Motors Peugeot Portadown	Door (Front) - Remove & Refit, Door mirror glass left - Electrically Controlled/Heated
Odo Reading	52197	
Invoice No.	0WI00058	
Authority Ref.	7509796	
Job Ref.	101326186	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
19 Nov 2019	Roadside Motors Peugeot Portadown	50000 mls/kms Service
Odo Reading	52197	
Invoice No.	9WI02685	
Authority Ref.	7493497	
Job Ref.	101162136	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
14 Nov 2019	ATS CH ARVAL DEALERS	P 1 Continental 215/60 R 17 T VAN CONTAC200 (BA2-72dB)
Odo Reading	51564	P 1 Tyre Valve
Invoice No.	10731952	P 1 Wheel Balance
Authority Ref.		P 1 Casing Disposal
Job Ref.	6969961	P 1 Continental 215/60 R 17 T VAN CONTAC200 (BA2-72dB)
Job Status	Complete	P 1 Tyre Valve
		P 1 Wheel Balance
		P 1 Casing Disposal

Date	Service Centre	Line Item Description
26 Jun 2019	Roadside Motors Peugeot Portadown	25000 mls/kms Service
Odo Reading	27185	Adblue - Remove & Refit, AdBlue fluid
Invoice No.	9WI01491	
Authority Ref.	7345414	
Job Ref.	98295306	
Job Status	Payment Requested	