



42a Greenhill Road, Ligonell,
Belfast BT14 8SH

TEL: 028 9082 5488 / 028 9082 5555

FAX: 028 9082 5657

www.briangrantcommercials.co.uk

Date In: 7-7-24	Date Out: 3-7-24
Repair Order No.:	
Customer's Name:	
Address: 107 Rm	
Type/Model.: 210 Euro 6	
Chassis No.: XLACL2500LLS6424	
Registration No.: 2466 RDM	
Mileage: 123000	KM/Miles
Last Calibration Date of Tachograph: 24/8/22	

Commercial Truck Inspection Sheet

TM No.	Tyres	
7	Size and type of tyre: Front 265-70 R15	Rear 235-70 R15
8	TYRE PRESSURES State - Pressures in bar Front Rear	TREAD WEAR State - Tread depth in mm Front Rear

☒ Servicable	☒ Item require attention	☒ N/A Not applicable	☒ TM VI Inspection Manual Item No.
--	--	--	--

TM No.	Cab Interior
1 / 2	Ministry plate position detail
3	Seat belts operation, condition
17	Cab floor and steps
18	Driver's seat condition and security
23	View to Front
24	Condition of windscreen and windows
25	Windscreen wipers and washers
26 / 29	Tachograph / speedometer operation and seals
27	Audible warning
28	Driving Controls
30	Steering wheel free play
31 / 32	Steering wheel / column condition, security
34	Air pressure / vacuum warning
35	Air pressure / vacuum build up
37 / 38	Service brake pedal condition and operation
39	Hand-operated brake control valves
42	Electrical wiring, equipment and switches
	Cab Exterior
9	Front bumper condition, security
14	Condition of cab, mud wing and spray suppression
15	Cab mountings and security
16	Cab doors and hinges / locks
17	Cab floor (underside)
22	External mirrors
63	Front position lamps
67 / 68	Headlamps
	Engine Compartment
43	Engine mountings
45	Fuel lines and equipment
46	Exhaust manifold and downpipe
33	Speed limiter, condition, seals
	Vehicle General at Ground Level
6	Road wheels and hubs
8	Condition of tyres
9	Side and rear underrun guards

TM No.	Vehicle General at Ground Level (cont.)
11	Trailer coupling
14	Rear mud wings and spray suppression
19 / 20	Body security and condition
62	Rear marking and reflectors
64	Rear lamps (position light and fog lamps)
66	Direction indicators and hazard warning lamps
69	Stop lamps
	Under Vehicle
41	Chassis condition
42	Electrical wiring and equipment
44	Oil leaks from units
45	Fuel tanks and lines
46	Exhaust system
48	Suspension pins and bushes
49 / 50	Suspension units and linkages condition
51	Shock absorbers security and condition
53	Stub axles and wheel bearings
54	Steering linkage
55	Air leaks
56	Power steering
57	Transmission and propeller shafts
	Brakes
59	Mechanical brake components
59	Brake actuators
59	Braking systems and components
74	Other dangerous defects
4	Brake linings
21	ABS
	TM Numbers as yet not allocated
40	
47	
52	
58	
75	

Brake Test Report (*delete as applicable)

ROAD SPEED LIMITER operational YES / NO * - set speed 70 kph*			
mph*			
Service	Imbalance	Axle 3	Parking
0.8 %	Axle 1 4 %	Axle 4 %	2.9 %
	Axle 2 8 %		
Tester's Name (Print) Gaby Mulholland		Tester's Signature	

Details and Comments, Items Requiring Attention

TM No.	Fault Details	Action Taken	Rectified By
	2. ABS fault	Repair not	
	4. N.S.C. Comp. Missing		
	Horn not working		

Inspection carried out by:	Signature	Date
Name (Print) Gaby Mulholland		7-7-24

I certify that the above inspection schedule has been completed, the defects listed *have / have not been rectified, and in my opinion the vehicle *is / is not in a roadworthy condition. (*delete as applicable)

This certificate relates only to the condition of the vehicle at the time of testing. It should not be regarded as evidence of the condition of the vehicle at any other time.

Name: Gaby Mulholland Date: 7-7-24

Signature: [Signature]

Position: Mechanic