

**McGales Garage**

2 Coolnagard Lane  
Dromore Road  
Omagh  
County Tyrone  
Northern Ireland  
BT78 1RG  
Tel: 02882243061  
Email: mcgalesgarage@aol.com

**Invoice I011987**

Date: 28-11-2025  
Job: J013421

**Vehicle**

**Registration:** WHZ7912  
**Volkswagen Amarok 2019 3.0 Diesel - GREY**

**Mileage:** 124310  
**VIN:** WV1ZZZ2HZKH010938

**Issues and Work  
Description**

**Work Description**  
Check for fault in E.M.S. - 15/05/2025- 23/05/2025

**Work performed**
**Labour**

| Labour                                                                                                                                                                                                                                                                                                                | VAT % | Net Total |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|-----------|
| Checking for E.M.L. on in dash. Bench testing all management systems & finding E.G.R. valve faulty. Removing faulty E.G.R. valve & fitting new one. Clearing all faults from all systems. Checking all oil levels & fluid levels and tapping up as necessary. Road testing vehicle for 60 miles & rechecking vehicle. | 20.00 | 327.00    |

| Parts                | Qty  | Unit Price | VAT % | Net Total |
|----------------------|------|------------|-------|-----------|
| Computer Diagnostics | 1.00 | 35.00      | 20.00 | 35.00     |
| Gasket               | 1.00 | 6.86       | 20.00 | 6.86      |
| Gasket               | 1.00 | 5.15       | 20.00 | 5.15      |
| Seal Ring            | 2.00 | 4.46       | 20.00 | 8.92      |
| EGR Cooler/Valve     | 1.00 | 795.63     | 20.00 | 795.63    |
| Gasket               | 1.00 | 28.50      | 20.00 | 28.50     |
| Pink AntiFreeze      | 3.00 | 3.97       | 20.00 | 11.91     |

**Labour SubTotal £1,218.97**

**Invoice Total**

| VAT | Code | Rate % | Net Total | VAT Total |
|-----|------|--------|-----------|-----------|
|     | (1)  | 20.00  | 1,218.97  | 243.79    |

Labour 327.00  
Parts 891.97  
VAT 243.79

**Invoice Total £1,462.76**

\*NOW DOING TYRES\*

ASK/RING FOR A COMPETITIVE PRICE

Bank Details, Santander, Sort Code - 09-01-27, Account Number - 83193280

Title to the goods supplied remain with this company until payment for them has been satisfactorily received - E & O E. Terms & Conditions available upon request

**McGales Garage**

2 Coolnagard Lane  
Dromore Road  
Omagh  
County Tyrone  
Northern Ireland  
BT78 1RG

Tel: +442882243061

Email: mcgalesgarage@aol.com • Web: <https://www.mcgalesgarage.com>

**Invoice I012374**

Date: 29-05-2026

Job: J013216

**Vehicle**

**Registration:** WHZ7912

Volkswagen Amarok 2019 3.0 Diesel - GREY

**Mileage:** 124310

**VIN:** WV1ZZZ2HZKH\*\*\*\*\*

**Issues and Work  
Description**
**Work Description**

Check for fault in E.M.S. - 24/09/2025

**Work performed**
**Parts**
**Labour**

Checking for fault in E.M.S, finding Ad Blu injector faulty. Removing faulty injector & fitting new one. Clearing all faults from all systems and road testing same.

**VAT %**    **Net Total**  
20.00    136.25

**Parts**

AD Blue Injector Valve  
Ad Blue Injector Clamp  
Computer Diagnostics

| Qty  | Unit Price | VAT % | Net Total |
|------|------------|-------|-----------|
| 1.00 | 444.60     | 20.00 | 444.60    |
| 1.00 | 6.25       | 20.00 | 6.25      |
| 1.00 | 35.00      | 20.00 | 35.00     |

**Parts SubTotal**    **£622.10**

**Invoice Total**

| VAT Code | Rate % | Net Total | VAT Total |
|----------|--------|-----------|-----------|
| (1)      | 20.00  | 622.10    | 124.42    |

Labour    136.25  
Parts    485.85  
VAT    124.42

**Invoice Total**    **£746.52**

\*NOW DOING TYRES\*

ASK/RING FOR A COMPETITIVE PRICE

Bank Details, Santander, Sort Code - 09-01-27, Account Number - 83193280

Title to the goods supplied remain with this company until payment for them has been satisfactorily received - E & O E. Terms & Conditions available upon request

## McGales Garage

2 Coolnagard Lane  
Dromore Road  
Omagh  
County Tyrone  
Northern Ireland  
BT78 1RG  
Tel: 02882243061  
Email: mcgalesgarage@aol.com

## Invoice I011775

Date: 03-10-2025  
Job: J011939

### Vehicle

Registration: WHZ7912

Volkswagen Amarok 2019 3.0 Diesel - GREY

Mileage: 116818

VIN: WV1ZZZ2HZKH010938

### Issues and Work Description

#### Work Description

Check vehicle over for MOT - 16/09/2024  
Check for fault in engine management system - 16/09/2024

### Work performed

#### Labour

##### Labour

Cleaning vehicle for MOT. Checking all brakes. Removing worn rear brake pads, cleaning & freeing callipers, cleaning discs & fitting new pads. Removing faulty rear s/absorbers & fitting new one. Removing worn front brake pads, removing callipers, cleaning & freeing as necessary. Removing faulty discs & fitting new ones, fitting callipers with new brake pads. Checking for fault in E.M.S. bench testing all systems. Removing faulty nox sensor & fitting new one. Checking all lights & fitting required bulbs. Setting H/lights. Clearing all faults from all management systems. Road testing vehicle.

VAT % Net Total  
20.0 463.25

##### Parts

|                            | Qty  | Unit Price | VAT % | Net Total |
|----------------------------|------|------------|-------|-----------|
| Front Brake Pad Set        | 1.00 | 115.43     | 20.0  | 115.43    |
| Front Brake Disc           | 2.00 | 76.54      | 20.0  | 153.08    |
| Rear Brake Pad Set         | 1.00 | 75.03      | 20.0  | 75.03     |
| Rear Shock Absorber        | 2.00 | 90.10      | 20.0  | 180.20    |
| Nox Sensor                 | 1.00 | 693.72     | 20.0  | 693.72    |
| Osram HID Xenon D8S Bulb   | 1.00 | 85.85      | 20.0  | 85.85     |
| Light Good Vehicle MOT Fee | 1.00 | 38.00      | 0.0   | 38.00     |
| MOT Wash                   | 1.00 | 30.00      | 20.0  | 30.00     |
| Computer Diagnostics       | 1.00 | 35.00      | 20.0  | 35.00     |
| Headlight Alignment        | 1.00 | 15.00      | 20.0  | 15.00     |

Labour SubTotal £1,884.56

### Invoice Total

#### VAT

| Code | Rate % | Net Total | VAT Total |
|------|--------|-----------|-----------|
| (1)  | 20.00  | 1,846.56  | 369.32    |
| (0)  | 0.00   | 38.00     | 0.00      |

Labour 463.25  
Parts 1,421.31  
VAT 369.32

Invoice Total £2,253.88

## McGales Garage

2 Coolnagard Lane  
Dromore Road  
Omagh  
County Tyrone  
Northern Ireland  
BT78 1RG  
Tel: 02882243061  
Email: mcgalesgarage@aol.com

## Invoice I010657

Date: 30-08-2024  
Job: J011200

### Vehicle

Registration: WHZ7912

Volkswagen Amarok 2019 3.0 Diesel - GREY

Mileage: 98223

VIN: WV1ZZZ2HZKH010938

### Issues and Work Description

#### Work Description

Carry out service on vehicle - 06/02/2024  
Check for handbrake not working on vehicle - 06/02/2024  
Remove and replace P/S/R tail lamp - 06/02/2024  
Check damage to P/S/R bumper and parking sensor - 06/02/2024  
Check for Off road light coming on in dash of vehicle - 06/02/2024

### Work performed

#### Labour

##### Labour

Carrying out service to vehicle. Checking all brakes, finding both o/s and n/s/r brake callipers faulty, removing faulty calliper and fitting new ones, bleeding all brakes. Removing excessively worn front A.R.B bushing and fitting new one. Checking for fault in 4wd system. Bench testing all management systems, cleaning all systems and relearning system. Checking all lights and setting H/Lights. Clearing all faults from all management system and setting service light. Road testing vehicle. Repairing n/s/r bumper section and fitting new park sensor. Removing damaged n/s/r S.T.F lamp and fitting new one. Retorquing all wheels and cleaning vehicle.

| VAT % | Net Total |
|-------|-----------|
| 20.0  | 400.00    |

##### Parts

|                                  | Qty  | Unit Price | VAT % | Net Total |
|----------------------------------|------|------------|-------|-----------|
| N/S/R Tail Light                 | 1.00 | 183.98     | 20.0  | 183.98    |
| Oil Filter                       | 1.00 | 16.53      | 20.0  | 16.53     |
| Air Filter                       | 1.00 | 25.25      | 20.0  | 25.25     |
| Fuel Filter                      | 1.00 | 34.15      | 20.0  | 34.15     |
| D/S/R Brake Caliper              | 1.00 | 207.01     | 20.0  | 207.01    |
| P/S/R Brake Caliper              | 1.00 | 207.03     | 20.0  | 207.03    |
| Anti-Roll bar bush               | 2.00 | 7.79       | 20.0  | 15.58     |
| Bosch Aero Wiper Blade - 24 inch | 2.00 | 14.20      | 20.0  | 28.40     |
| Headlight Alignment              | 1.00 | 15.00      | 20.0  | 15.00     |
| Computer Diagnostics             | 1.00 | 35.00      | 20.0  | 35.00     |
| 5W30 Engine Oil                  | 8.00 | 5.75       | 20.0  | 46.00     |
| Brake Fluid                      | 1.00 | 8.00       | 20.0  | 8.00      |
| Vehicle Wash                     | 1.00 | 10.00      | 20.0  | 10.00     |

Labour SubTotal £1,231.93

### Invoice Total

| VAT Code | Rate % | Net Total | VAT Total |
|----------|--------|-----------|-----------|
| (1)      | 20.00  | 1,231.93  | 246.40    |

|        |        |
|--------|--------|
| Labour | 400.00 |
| Parts  | 831.93 |
| VAT    | 246.40 |

## McGales Garage

2 Coolnagard Lane  
Dromore Road  
Omagh  
County Tyrone  
Northern Ireland  
BT78 1RG  
Tel: 02882243061  
Email: mcgalesgarage@aol.com

## Invoice I009884

Date: 29-12-2023  
Job: J010680

### Vehicle

**Registration:** WHZ7912  
**Volkswagen Amarok 2019 3.0 Diesel - GREY**

**Mileage:** 91177

**VIN:** WV1ZZZ2HZKH010938

### Issues and Work Description

#### Work Description

Check vehicle over for MOT - 14/09/2023

### Work performed

#### Labour

##### Labour

Cleaning vehicle for MOT. Carrying out complete check of vehicle for MOT, checking all brakes, removing worn front brake pads, cleaning and freeing callipers, cleaning discs and fitting new pads, cleaning all brake pipes. Checking all light and setting H/ Light. Cleaning all faults from all management systems, road testing and showing at MOT centre. Regen light came on when going to MOT centre and was turned down for this reason, carrying out regen and showing at MOT centre for retest.

| VAT % | Net Total |
|-------|-----------|
| 20.0  | 240.00    |

##### Parts

Light Good Vehicle MOT Fee  
Front Brake Pad Set  
MOT Retest Fee  
MOT Wash  
Headlight Alignment  
Computer Diagnostics

| Qty  | Unit Price | VAT % | Net Total |
|------|------------|-------|-----------|
| 1.00 | 30.50      | 0.0   | 30.50     |
| 1.00 | 109.35     | 20.0  | 109.35    |
| 1.00 | 18.50      | 0.0   | 18.50     |
| 1.00 | 25.00      | 20.0  | 25.00     |
| 1.00 | 15.00      | 20.0  | 15.00     |
| 1.00 | 20.00      | 20.0  | 20.00     |

**Labour SubTotal £458.35**

### Invoice Total

| VAT Code | Rate % | Net Total | VAT Total |
|----------|--------|-----------|-----------|
| (1)      | 20.00  | 409.35    | 81.87     |
| (0)      | 0.00   | 49.00     | 0.00      |

|        |        |
|--------|--------|
| Labour | 240.00 |
| Parts  | 218.35 |
| VAT    | 81.87  |

**Invoice Total £540.22**

\*NOW DOING TYRES\*

ASK/RING FOR A COMPETITIVE PRICE

Bank Details, Santander, Sort Code - 09-01-27, Account Number - 83193280

Title to the goods supplied remain with this company until payment for them has been satisfactorily received - E & O E. Terms & Conditions available upon request

**McGales Garage**

2 Coolnagard Lane  
Dromore Road  
Omagh  
County Tyrone  
Northern Ireland  
BT78 1RG  
Tel: 02882243061  
Email: mcgalesgarage@aol.com

**Invoice I009166**

Date: 31-03-2023  
Job: J0009998

**Vehicle** Registration: WHZ7912 Mileage: 79864  
Volkswagen Amarok 2019 3.0 Diesel - GREY VIN: WV1ZZZ2HZKH010938

**Issues and Work Description**  
Work Description  
Carry out full service on vehicle - 20/02/2023

**Work performed**  
**Parts**

**Labour** VAT % Net Total  
Carrying out service to vehicle. Checking all brakes, cleaning all brake pipes. 20.0 122.50  
Checking all lights, setting H/lights. Clearing all faults from all management systems.  
Setting service light. Road testing vehicle & retorquing all wheels.

| Parts                   | Qty   | Unit Price | VAT % | Net Total |
|-------------------------|-------|------------|-------|-----------|
| Oil Filter              | 1.00  | 16.53      | 20.0  | 16.53     |
| Fuel Filter             | 1.00  | 33.94      | 20.0  | 33.94     |
| Air Filter              | 1.00  | 25.11      | 20.0  | 25.11     |
| Ad Blue                 | 12.00 | 0.93       | 20.0  | 11.16     |
| 5W30 Low Sap Engine Oil | 8.00  | 5.75       | 20.0  | 46.00     |

**Parts SubTotal £255.24**

| Invoice Total | VAT Code | Rate % | Net Total | VAT Total |
|---------------|----------|--------|-----------|-----------|
|               | (1)      | 20.00  | 255.24    | 51.05     |

Labour 122.50

Parts 132.74

VAT 51.05

**Invoice Total £306.29**

\*NOW DOING TYRES\*

ASK/RING FOR A COMPETITIVE PRICE

Bank Details, Santander, Sort Code - 09-01-27, Account Number - 83193280

Title to the goods supplied remain with this company until payment for them has been satisfactorily received - E & O E. Terms & Conditions available upon request



McGALES  
GARAGE

### McGales Garage

2 Coolnagard Lane  
Dromore Road  
Omagh  
County Tyrone  
Northern Ireland  
BT78 1RG  
Tel: 02882243061  
Email: mcgalesgarage@aol.com

### Invoice I008746

Date: 31-10-2022

Job: J009385

#### Vehicle

Registration: WHZ7912  
Volkswagen Amarok 2019 3.0 Diesel - GREY

Mileage: 64329

VIN: WV1ZZZ2HZKH010938

#### Issues and Work Description

##### Work Description

Check vehicle over for MOT - 18/08/2022

#### Work performed

##### Parts

##### Labour

Cleaning vehicle for MOT, carrying out complete check of vehicle. Checking all brakes, cleaning all brake pipes as necessary. Checking all lights, setting H/Lights and showing at MOT centre.

VAT % 20.0  
Net Total 87.50

##### Parts

MOT Test Fee - Car  
Headlight Alignment

| Qty  | Unit Price | VAT % | Net Total |
|------|------------|-------|-----------|
| 1.00 | 30.50      | 0.0   | 30.50     |
| 1.00 | 15.00      | 20.0  | 15.00     |

Parts SubTotal £133.00

#### Invoice Total

##### VAT

| Code | Rate % | Net Total | VAT Total |
|------|--------|-----------|-----------|
| (0)  | 0.00   | 30.50     | 0.00      |
| (1)  | 20.00  | 102.50    | 20.50     |

|        |       |
|--------|-------|
| Labour | 87.50 |
| Parts  | 45.50 |
| VAT    | 20.50 |

Invoice Total £153.50

\*NOW DOING TYRES\*

ASK/RING FOR A COMPETITIVE PRICE

Bank Details, Santander, Sort Code - 09-01-27, Account Number - 83193280

Title to the goods supplied remain with this company until payment for them has been satisfactorily received - E & O E. Terms & Conditions available upon request

**McGales Garage**

2 Coolnagard Lane  
Dromore Road  
Omagh  
County Tyrone  
Northern Ireland  
BT78 1RG  
Tel: 02882243061  
Email: mcgalesgarage@aol.com

**Invoice I008205**

Date: 31-05-2022  
Job: J008749

**Vehicle**

**Registration:** WHZ7912  
**Volkswagen Amarok 2019 3.0 Diesel - GREY**

**Mileage:** 56936  
**VIN:** WV1ZZZ2HZKH010938

**Issues and Work  
Description**
**Work Description**

Carry out full service on vehicle - 15/02/2022

**Work performed**
**Labour**
**Labour**

Carrying out major service to vehicle. Checking all brakes. Removing all worn brake pads, cleaning calipers & discs & fitting new pads. Clearing all faults from all management systems. Setting service light & road testing.

**VAT %** **Net Total**  
20.0 175.00

**Parts**

|                          | Qty  | Unit Price | VAT % | Net Total |
|--------------------------|------|------------|-------|-----------|
| Oil Filter               | 1.00 | 15.33      | 20.0  | 15.33     |
| Fuel Filter              | 1.00 | 30.64      | 20.0  | 30.64     |
| Air Filter               | 1.00 | 22.99      | 20.0  | 22.99     |
| Front Brake Pad Set      | 1.00 | 97.65      | 20.0  | 97.65     |
| Rear Brake Pad Set       | 1.00 | 63.55      | 20.0  | 63.55     |
| 5W30 Low Saps Engine Oil | 8.00 | 5.75       | 20.0  | 46.00     |

**Labour SubTotal** **£451.16**

**Invoice Total**
**VAT**

| Code | Rate % | Net Total | VAT Total |
|------|--------|-----------|-----------|
| (1)  | 20.00  | 451.16    | 90.24     |

**Labour** 175.00

**Parts** 276.16

**VAT** 90.24

**Invoice Total** **£541.40**

\*NOW DOING TYRES\*

ASK/RING FOR A COMPETITIVE PRICE

Bank Details, Santander, Sort Code - 09-01-27, Account Number - 83193280

Title to the goods supplied remain with this company until payment for them has been satisfactorily received - E & O E. Terms & Conditions available upon request