

Work History

Registration/Fleet ID	IGZ4843	Asset No.	41936
Make/Model	Mitsubishi Shogun LWB Diesel 3.2 Di-dc SG2 Van Auto		
Latest Odo Reading	89454	Odo Reading Date	01 Oct 2026
Contract Start Date	06 Oct 2023	Contract End Date	05 Oct 2035

Date	Service Centre	Line Item Description
17 Apr 2026	Auto Clinic Belfast	Power steering leak investigation
Odo Reading	88245	Steering Unit - Remove & Refit, Rack and pinion/steering box - manual steering
Invoice No.	1989	Front And Rear Alignment - Check & Adjust, Wheel Alignment - front/rear
Authority Ref.	3155192	
Job Ref.	156299406	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
09 Mar 2026	Auto Clinic Belfast	Valet - Remove & Refit, Valet
Odo Reading	85441	Injection - Remove & Refit, Injection pump fuel rail
Invoice No.	1901	Exhaust Gas Analysis - Repair, Regeneration of Particulate Filter(s)
Authority Ref.	3151734	
Job Ref.	155024657	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
02 Feb 2026	Auto Clinic Belfast	Exhaust rattle + under tray hanging down. Repaired both on ramp.
Odo Reading	79343	
Invoice No.	1869	
Authority Ref.	3150646	
Job Ref.	153839161	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
19 Sep 2025	Donnelly Bros Newtownabbey (BT36 4AA)	Interim Service (1link)
Odo Reading	76046	Linings (Pads & Shoes) - Remove & Refit, Pads - rear (axle set)
Invoice No.	3737370	Disc - Remove & Refit, Disc (incl. pads) - rear (pair)
Authority Ref.	3146881	Front Arms (Upper & Lower) - Remove & Refit, Ball joint (Front Susp.) - upper left
Job Ref.	149794475	Front Anti-Roll Bar - Remove & Refit, Anti-roll/stabiliser bushes (Front Susp.)
Job Status	Payment Requested	Column - Remove & Refit, Column coupling/CV joint
		Alternator/Charging Circuit - Remove & Refit, Drive belt (alternator/dynamo)
		Air Conditioning System - Remove & Refit, Air Conditioning System - belt
		Lamps - Remove & Refit, Lamps exterior - rear lamp bulb
		Camshaft - Remove & Refit, Timing belt/chain with water pump
		Wash/Wipe Systems - Remove & Refit, Tailgate wiper - blade
		Wash/Wipe Systems - Remove & Refit, Windscreen wiper - blade left
		All Exhaust Components - Remove & Refit, Diesel particulate filter
		Turbocharger - Remove & Refit, Turbocharger gasket

Date	Service Centre	Line Item Description
17 Jan 2025	Vertu Hyundai Edinburgh West	Manufacturer Service - Time Based
Odo Reading	60000	Other Unspecified Work - Routine, Other
Invoice No.	12803064	Unspecified Repair
Authority Ref.	3139572	full check on brakes please
Job Ref.	142449048	Wash/Wipe Systems - Remove & Refit, Tailgate wiper - blade
Job Status	Payment Requested	Wash/Wipe Systems - Remove & Refit, Windscreen wiper - blade/s
		Sensors - Remove & Refit, Coolant Flush
		Disc - Remove & Refit, Disc (incl. pads) - front (pair)
		Front Arms (Upper & Lower) - Remove & Refit, Arm (Front Susp.) - lower assy/wishbone (both)
		Front Anti-Roll Bar - Remove & Refit, Anti-roll/stabiliser bushes (Front Susp.)
		Air Conditioning System - Remove & Refit, Air Conditioning System - charge/discharge
		Battery - Remove & Refit, Key Fob Battery
		Front And Rear Alignment - Check & Adjust, Wheel Alignment - front/rear

Date	Service Centre	Line Item Description
18 Sep 2024	Kwik Fit EV SMR Edin-Mcdonald Rd(218)	MOT - Class IV Cars (Up To 8 Passenger Seats) Test Date:17 Sep 2024 Certificate No:949260933319
Odo Reading	58325	
Invoice No.	YC778576	
Authority Ref.	3135470	
Job Ref.	139060073	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
24 Nov 2023	AA Breakdown	Breakdown
Odo Reading	55485	Mechanical Recovery
Invoice No.	0202389697	
Authority Ref.	3128516	
Job Ref.	130944940	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
21 Nov 2023	North City Autos Mitsubishi Chingford	Engine Management Fault Diagnosis - Check, Engine management - read fault codes
Odo Reading	55490	Engine Management Fault Diagnosis - Check, Fuel injection - read fault codes
Invoice No.	80505	Fuel Tank - Remove & Refit, Fuel tank
Authority Ref.	3126728	Filters - Remove & Refit, Fuel filter - complete
Job Ref.	130866848	Fuel Line - Remove & Refit, Fuel pipes/clips
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
02 Nov 2023	Prestige - Prestige Mot Centre	Checks - Check, Investigate & Report
Odo Reading	55490	Checks - Check, Investigate & Report
Invoice No.	1971853	
Authority Ref.	3127186	
Job Ref.	130343536	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
16 Oct 2023	Prestige - Prestige Mot Centre	Investigate & Report - diesel leak and cylinder 2 is misfiring
Odo Reading	55479	Other Unspecified Work - Routine, Other
Invoice No.	1945037	Unspecified Repair
Authority Ref.	3125439	Checks - Check, Investigate & Report
Job Ref.	129830425	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
07 Oct 2023	AA Breakdown	Breakdown
Odo Reading	55451	
Invoice No.	0202306450	
Authority Ref.	3127173	
Job Ref.	129631159	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
07 Oct 2023	AA Breakdown	Breakdown
Odo Reading	55451	
Invoice No.	0202306451	
Authority Ref.	3127172	
Job Ref.	129631160	
Job Status	Payment Requested	